


3/8" STANDARD WASHER

3/8" LOCK WASHER

3/8"-16 x 2" LONG
SOCKET HEX HEAD BOLT
1 REQUIRED

Assembly instructions for
K29

1/4"-20 x 1/2" LONG
PAN CROSS HEAD SCREW
2 REQUIRED FOR THIS STEP
(LEAVE THESE SCREWS LOOSE
FOR EASE OF ASSEMBLY)



NOTE: BALL STOPS
NOT SHOWN FOR CLARITY.
THEY MUST FACE UP.

RETAIL
WR Display & Packaging
SUPPLIES
WWW.RETAILSUPPLIES.NET


Assembly instructions for
240029.



1/4" -20 x 1/4" LONG
SOCKET HEAD SET SCREW
2 REQUIRED FOR THIS STEP
(LEAVE THESE SCREWS LOOSE
FOR EASE OF ASSEMBLY)

RETAIL
WR Display & Packaging
SUPPLIES
WWW.RETAILSUPPLIES.NET

Assembly instructions
for 240029.



TIGHTEN ALL SCREWS TO FIX
RACK COMPONENTS INTO PLACE.

RETAIL
WR Display & Packaging
SUPPLIES
WWW.RETAILSUPPLIES.NET

Assembly instructions
for 240029.